

## FLAIRMO OXYGEN MONITOR



Solution 1



Solution 2

The FLAIRMO oxygen monitor is a plug-and-play oxygen purity monitor can be used for both nitrogen and oxygen generators, depending on the system you operate. It shows oxygen purity (0.5–100%) on a 1.5" LCD display. **The monitor comes in two different solutions**

- **Solution 1:** With display
- **Solution 2:** With display and a visual purity indicator and buzzer alarm

The visual purity alarm indicator is a status lamp that indicate whether purity is above or below your specified value.

The monitor comes with universal power input (100–240V / 50–60Hz) and Ø6 mm push-fit connection hose for easy installation.

## Specifications

Display	1,5" LCD
Voltage / Frequency	100-240V / 50-60Hz
Measurement-Display	0,5-100% oxygen purity
Sampling	Ø6 mm push-fit connection hose
Alarms-Indication	Red/green lamps triggered by threshold
LxWxH	610 x 244 x 650 mm
Weight	36 Kg

### Instant status indicator

- Green = Purity OK
- Red = Requires attention

### Easy installation

- Plug-and-play solution

### Reliable operation

- Clear display for operators – reduces errors and waste